





TOOLSHED PREMIUM / EDGE

3,36 x 1,36 x 2,20 M




S1


x26



M6x16




S1 x1
M6x16




S1




x3



M6x16




S1 x12
M6x16




S1




x3



M6x16




S1 x13
M6x16





S1

x9




M6x16






S1

x7




M6x16






S1


x7



M6x16




S1	x16	S3	x2
			
M6x16		M4x10	




S1



x4






M6x16



TAPE




S1 x16
M6x16





S1


x7






M6x16











A detailed line drawing of a bolt and nut assembly. The bolt is shown from a side-on perspective, featuring a hexagonal head with a central hole and a threaded shaft. A nut is threaded onto the end of the bolt, also shown from a side-on perspective.



S1	x16	S4	x4
			
M6x16		M6x12	










S1

x40






M6x16





S2	x8	S3	x16
			
M5x10		M4x10	



S4	x9	S2	x6	S3	x2
					
M6x12		M5x10		M4x10	

